



GEOTECHNICAL & MATERIALS
ENGINEERING, TESTING & INSPECTION
P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No.1450

SIEVE ANALYSIS

PROJECT: Product Check – Four Corners
P.O. No. 7001-95000
CLIENT: Kimmins Contracting Corporation

PROJECT NO: TL-8047
DATE: March 18, 2014

SAMPLE LOCATION: Stockpiled at Four Corners Processing Facility


SAMPLE DESCRIPTION: Limestone Ballast

<u>Sieve Number</u>	<u>Percent Passing</u>
4"	100
3½ "	99
3"	97
2½ "	93
2"	78
1½ "	51
1"	7
¾ "	4

DATE RECEIVED: 3/04/14

DATE TESTED: 3/14/14

REPORTS TO:
Email:
cagosto@kimmins.com



dl'svs.385

This report contains information that is intended solely for the use of the client and noted assigns.
This report shall not be reproduced, except in full, without written approval of Test Lab, Inc.