



ENGINEERING, TESTING & INSPECTION
P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No. 1450

Product Check - P.O. No. 7001-95000 PROJECT:

53rd St. Yard

Transcor Recycling LLC **CLIENT:**

PROJECT NO:

TL-8047

DATE:

6/8/2016

LAB NO:

21453

SAMPLE LOCATION:

Stockpiled at 53rd St. Yard

SAMPLE DESCRIPTION:

No. 57 Crushed Concrete

Sieve Number	Percent Passing
1 1/2"	100
1"	86
3/4"	47
¹ / ₂ "	11
³ / ₈ "	5
No. 4	4
No. 8	4

FINENESS MODULUS: 7.41

DATE SAMPLED:

5/31/16

DATE TESTED:

6/2/16