



GEOTECHNICAL & MATERIALS
 ENGINEERING, TESTING & INSPECTION
 P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No.1450

SIEVE ANALYSIS

PROJECT: Product Check
 53rd St. Yard
CLIENT: Transcor Recycling LLC

PROJECT NO: TL-8047
DATE: 11/10/2017
LAB NO.: B-11035

SAMPLE LOCATION: Stockpiled at 53rd Street Yard
SAMPLE DESCRIPTION: Limestone Ballast

<u>Sieve Number</u>	<u>Percent Passing</u>
5"	100
4"	100
3"	93
2 ^{1/2} "	82
2"	62
1 ^{1/2} "	26
1"	4
3/4"	3

DATE SAMPLED: 11/1/17

DATE TESTED: 11/7/17

