



SIEVE ANALYSIS

GEOTECHNICAL & MATERIALS
ENGINEERING, TESTING & INSPECTION
P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No.1450

PROJECT: Product Check PROJECT NO: TL-8047
53rd St. Yard
CLIENT: Transcor Recycling LLC DATE: January 14, 2014

SAMPLE LOCATION: Stockpiled at 53rd Street Processing Facility

SAMPLE DESCRIPTION: Fine aggregate SAND


<u>Sieve Number</u>	<u>Percent Passing</u>
No. 4	100
No. 8	100
No. 16	100
No. 30	95
No. 50	54
No. 100	9
No. 200	0.4

FINENESS MODULUS: 1.43

DATE SAMPLED: 1/10/14

DATE TESTED: 1/11/14

REPORTS TO:
Email:
Candice Agosto at cagosto@transcorrecycling.com



d\lsvs.367