



**GEOTECHNICAL & MATERIALS  
ENGINEERING, TESTING & INSPECTION**  
P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No.1450

**SIEVE ANALYSIS**

**PROJECT:** Product Check - P.O. No. 7001-95000  
53<sup>rd</sup> St. Yard

**PROJECT NO:** TL-8047

**CLIENT:** Transcor Recycling LLC

**DATE:** 11/9/2017

**LAB NO.:** B-11034

**SAMPLE LOCATION:** Stockpiled at 53<sup>rd</sup> Street Yard

**SAMPLE DESCRIPTION:** Coarse Aggregate – No. 57 Limestone

<u>Sieve Number</u>	<u>Percent Passing</u>	<u>No. 57 Aggregate ASTM C 33</u>
1 1/2"	100	100
1"	91	95-100
3/4"	74	—
1/2"	42	25-60
3/8"	24	—
No. 4	12	0-10
No. 8	6	0-5

**FINENESS MODULUS:** 6.85

**DATE SAMPLED:** 11/1/17

**DATE TESTED:** 11/8/17

