



**GEOTECHNICAL & MATERIALS  
ENGINEERING, TESTING & INSPECTION**  
P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821 CA No.1450

**SIEVE ANALYSIS**

**PROJECT:** Product Check  
53<sup>rd</sup> Street Yard

**PROJECT NO:** TL-8047

**CLIENT:** Transcor Recycling LLC

**DATE:** 11/9/2017

**LAB NO.:** B-11033

**SAMPLE LOCATION:** Stockpiled at 53<sup>rd</sup> Street Yard

**SAMPLE DESCRIPTION:** Coarse Aggregate – No. 89 Limestone

<u>Sieve Number</u>	<u>Percent Passing</u>	<u>No. 89 Aggregate ASTM C 33</u>
1/2"	100	100
7/8"	97	90-100
No. 4	43	20-55
No. 8	7	0-30
No. 16	3	0-10
No. 30	2	—
No. 50	1	0-5
No. 100	1	—

**FINENESS MODULUS:** 5.46

**DATE SAMPLED:** 11/1/17

**DATE TESTED:** 11/8/17

