

GEOTECHNICAL & MATERIALS

ENGINEERING, TESTING & INSPECTION P.O. BOX 15732 • TAMPA, FLORIDA 33684 • 813/872-7821

PROJECT: Product Check - P.O. No. 7001-95000

53rd Street Yard

CLIENT: Transcor Recycling LLC DATE:

PROJECT NO:

TL-8047

6/27/2017

LAB NO .:

22317

SAMPLE LOCATION:

Stockpile at 53rd Street Yard

SAMPLE DESCRIPTION:

Crushed Concrete (Base Material)

Material Type B-12 **FDOT Specifications** Uncertified Sieve Number Percent Passing 11/2" 100 3/411 89 65-95 3/27 40-85 69 54 25-65 No. 4 No.10 20-50 44 5-30 No. 50 28 No. 100 16 No. 200 7.1 0-10

ATTERBERG LIMITS:

LL: NP

PL: NP

PI: NP

DATE SAMPLED:

6/19/17

DATE TESTED:

6/22/17



ENGINEERING, TESTING & INSPECTION


P.O. BOX 15732 - TAMPA, FLORIDA 33684 - 813/872-7821 CA No. 1450

Product Check - P.O. No. 7001-95000

53rd St. Yard

CLIENT:

Transcor Recycling LLC



130.0 125.0 DRY UNIT WEIGHT, (PCF) 120.0 115.0 110.0 105.0 100.0 95.0 **MOISTURE CONTENT (%)**

LIMEROCK BEARING RATIO TEST TEST METHOD: FDOT FM 5-515

PROJECT NO:

TL-8047

DATE:

June 27, 2017

LAB NO:

22317

LBR TEST NO:

168

COMPACTION TEST NO.:

192

MAXIMUM LBR VALUE (%):

210

MAXIMUM DRY DENSITY (PCF):

118.7

OPTIMUM MOISTURE (%):

9.6

DATE RECEIVED:

06/19/17

DATE TESTED:

06/26/17

LOCATION SAMPLED: Stockpile at 53rd St. Yard

SOIL DESCRIPTION:

Crushed Concrete

TYPE OF MATERIAL: Base

SOAKING TIME (HRS):

48±4

SOAKING SURCHARGE (LBS): TESTING SURCHARGE (LBS):

2.5

REMARKS:

This report contains information that is intended solely for the use of the client This report shall not be reproduced, except in full, without written approval of